




YLS-4A

SCREEN WINDOW







PRODUCT USER MANUAL




Installation tools



$\varphi=6\text{mm}$
 $\varphi=2.8\text{mm}$





Product Struction




Assembly




A




C



D



E1



E2



F*12



J*4




H




I*2


1


 $H = \min (H1 \ H2 \ H3)$
 $W = \min (W1 \ W2 \ W3)$


2





3



4




5




6

LEFT


RIGHT




7




8




9




10



11



12



13

